

Risto Minovski
Voislav Jankov
A. Laskov
K. Andov
Electrotechnical Faculty, Skopje

OVERVIEW OF EXPLOITATION PROBLEMS OF 36 KV FEEDER TO FURNACE 2 IN FENI -INDUSTRIES

ABSTRACT

This paperwork is result of the analyzing the causes for failures which several years are problem at 36 kV cable lines, that connects transformer and industrial furnace. Between 1993 and 2003 there were 16 faults on the cable endings (accessories) which is unacceptable. In failure analysis was included high number of important factors that influence on insulation of cable endings.

Keywords: Cable accessories.